



ACTi KCM series

Firmware Release Notes

Version 5.11.17

2013/11/20



ACTi
Connecting Vision

Legal Notice

Disclaimer

- The information contained in this document is intended for general information purposes. ACTi Corporation shall not be liable for errors contained herein or for incidental or consequential damages arising from the furnishing, performance, or use of this document.
- The information contained herein is subject to change without notice.

Copyright

Copyright ©2003-2013 ACTi Corporation All Rights Reserved.

Contents

1 Firmware Version 4

New Features.....	4
Enhancements	6
Issue Solved	7
Supported languages.....	7
Remark	7
Limitation.....	8

2 Upgrade 9

New ISP firmware Version.....	9
Camera Firmware Upgrade Procedure	10
ISP Firmware Upgrade Procedure	12

3 Download and Documentation 17

4 Support 17

Firmware Version


Firmware Version: [A1D-311-V5.11.17-AC](#)

Release Date: 2013.10.24

New Features

1. (V5.11.17) Add touring speed setting on PTZ control panel
2. (V5.09.15) Support 1/5 Slowest Auto Shutter for KCM-3311, KCM-3911, KCM-5111, KCM-5211E, KCM-5311E, KCM-5511, KCM-5611, KCM-7111, KCM-7311 and KCM-7911.

(After upgrading the camera and ISP firmware, please factory reset the camera to support 1/5 shutter speed by default.)



3. (V5.09.15) Support FisheyeView mode for KCM-3911 and KCM-7911. User can adjust the shooting angle of double-panorama at ceiling mount type, and tilt angle of panorama at Wall-Mount type.


2.1 In FisheyeView mode, camera just could serve single format video stream which the video image is panorama view image. The available video resolutions is 2032x1936 only. The remote client has to de-wrap the video stream from camera to help people understand the video image. There is no fisheye control functions like rotation, installation angle adjustment and PTZ in this mode.

2.2 Get into the fisheye installation setup by visiting "Camera Options" page in the camera WEB page. You can set suitable installation configurations based on their environment to get the correct video image.

The Mounting Type configuration is available in all video streaming modes.

In single or dual streaming mode, with wall mount installation, the installation angle adjustment is available. The rotation configuration is available with ceiling mount installation.

In ePTZ and MD_PRESET streaming modes, the installation angle and rotation configuration are not shown.



4. (V5.09.15) Full-function support for KCM-8111 and KCM-8211
5. (V5.09.15) Support AutoFlip and DigitalZoom for KCM-8111 and KCM-8211 (After upgrading the camera and ISP firmware, please factory reset the camera. The feature is disabled by default.)

Enhancements

1. (V5.11.17) PT speed on-fly change in ActiveX controller
2. (V5.11.17) Zoom speed on-fly
3. (V5.11.17) Filter burst zoom commands
4. (V5.11.17) Set the zooming boundary by URL ZOOM_LIMIT in KCM-8111 and KCM-8211
5. (V5.11.17) Back to specific home or a preset point after an idle timer expired
6. (V5.11.17) Keep preset configuration when change the camera streaming mode in fisheye camera
6. (V5.11.17) Follow Onvif RTP extension to support MJPEG RTP with resolution higher than 2040x2040.
7. (V5.11.17) ONVIF PTZ compatibility
8. (V5.09.15) Compliant with ONVIF Core Specification v2.2
9. (V5.09.15) Increased the maximum Pre-Buffer Time to 10 seconds for upload video in event handler function.
10. (V5.09.15) Support PELCO-P PTZ Protocol
11. (V5.09.15) GET_STREAM URL command also can be supported for user account and root account.
12. (V5.08.06) Support Event to Local Storage
 - Save Video or snapshot to local storage by event handler triggered sources(Schedule, Digital Input, Motion Detection, Camera power on)
 - Search / download / delete files in local storage from device's Web Configuration directly.
13. (V5.08.06) Support "@" in Email account name.
14. (V5.08.06) The IPv6 address will be read from System Info page on camera web configurator.
15. (V5.08.06) Support new model: KCM-8111.
16. (V5.07.05) Support new model: KCM-7911.
17. (V5.07.05) Support Audio format :G.711 aLaw / uLaw
18. (V5.07.05) Support RTP over RTSP , RTP over HTTP
19. (V5.07.05) Compliant to ONVIF V2.0 (the function is enabled by default)
 - IP Configuration
 - Device Discovery
 - Device Management
 - Media Configuration

- Video/Audio Stream
 - PTZ control
 - Event Management (Motion Detection, Digital Input)
20. (V5.07.05) Add the warning message "IP Address and Gateway are not in the same subnet." to prevent incorrect network configuration.

Issue Solved

1. (V5.11.17) When camera is static IP address, SMTP domain name server address does not work.
2. (V5.11.17) Camera is unstable when using RTSP streaming
3. (V5.11.17) URL command "Focus=Auto" is unable to change camera to Auto focus mode.
4. (V5.11.17) Camera bitrate/frame may be uncontrollable in RTP multicast streaming
5. (V5.11.17) Script error when clicking PTZ button via non-root account user on Web Configurator
6. (V5.11.17) Remove the text "Stream" of the "STREAMING MODE = Single Stream" in SYSTEM_INFO
7. (V5.10.02) Memory leak issue with Onvif integration
8. (V5.09.15) Device may revert to default settings under particular conditions.
9. (V5.09.15) Tilt function may not work properly.
10. (V5.09.15) SEND_AUDIO URL command doesn't play audio correctly.
11. (V5.09.15) KCM-8111 with earlier ISP version 1.04.04 duplicated frame issue at 720P and VGA.
12. (V5.07.05) Serial setting will be reset to default setting (port control: 8, None, 1 / baud rate :9600) after rebooting the camera

Supported languages

Czech, Dutch, English, French, Hungarian, Italian, Japanese, Polish, Romanian, Russian, Spanish, Simplified Chinese and Traditional Chinese.

Remark

1. Motion sensitivity should be 70 or above for effective motion detection.

2. No Variable Frame Rate mode. This function is only available on earlier ACM series models, our new models (TCM/KCM/D/E/B/I series) already have dual stream capability.
3. Motion Detection not available for “MJPEG” encoder type and MD Preset stream mode.
4. Motion Detection, Event handler, get the snapshot via URL command, and home position functions are not available in “MD Preset” stream mode.
5. Privacy Mask function is available for stream 1 only.
6. Privacy Mask can configure full image area in 1280x720 and 640x480. For higher resolution, privacy mask could not mask the area out of 1270x1023.
7. In dual streams mode, the frame rate in stream 1 has to be lower or equal to stream 2. Otherwise, the actual frame rate in stream 1 will be limited to the stream 2 frame rate.
8. Please save and reboot the device after remove HTTPS certificate files.
9. PTZ control panel in web UI can configure up to 32 preset points and 32 preset tour points in a tour group. You can configure the additional preset points up to 32 by using PTZ URL command.
10. The default PTZ protocol is ACTi/VISCA. The available PTZ protocols are ACTi/VISCA, SONY/VISCA, PELCO/PELCO, PELCO/PELCO.
11. ONVIF Profile S will be supported in future version

Limitation

1. The RTP Multicast Video/Audio must be even numbers on KCM FW v5.02.26 and above. If the original FW version is V5.01.07 before FW upgrading, you may need to change the ports manually in “Port Mapping” page or do the factory default manually .
2. Please enable “RTP B2 Frame” on camera to prevent compatibility problem with software NVR or standalone NVR.
3. For Microsoft Internet Explorer 10.0 or newer version, please enable “Compatibility View” on the Tools menu to connect to the camera’s web configurator.
4. The video frame rate might not reach to the expected video frame rate after shutter speed synchronization.
5. After changing resolution, you may need to configure camera’s Motion

Detection and Privacy Mask setting again.

Upgrade

To achieve the best possible functionality and video quality of the camera, both camera firmware and the ISP firmware should be upgraded.

You can use the IP Utility 4.2.04 or later version to upgrade both camera firmware and ISP conveniently and can upgrade multiple cameras at the same time using IP Utility.

New ISP firmware Version

KCM Models		Camera Firmware	ISP		IP Utility
			ISP Firmware	ISP Resource	
KCM-5111	Version	V5.11.17	V1.03.06	V1.03.06	V4.2.04
KCM-7111	Filename	A1D-311-V5.11.17-AC.upg	ISP-F-0100-V1.03.06.bin	C0100-V1.03.06.bin	and later
KCM-5211					

No new ISP firmware for discontinued products (KCM-3211, KCM-5311 and KCM-7211)

KCM Models		Camera Firmware	ISP			IP Utility
			ISP Firmware	ISP Resource	ISP Hardware	
KCM-3911	Version	V5.11.17	V1.05.05	V1.05.05	V1.00.13	V4.2.04
KCM-7911	Filename	A1D-311-V5.11.17-AC.upg	ISP-U-0200-V1.05.05.bin			and later

KCM Models		Camera Firmware	ISP			IP Utility
			ISP Firmware	ISP Resource	ISP Hardware	
KCM-5211E	Version	V5.11.17	V1.05.01	V1.05.01	V1.00.11	V4.2.04
KCM-5311E	Filename	A1D-311-V5.11.17-AC.upg	ISP-U-0300-V1.05.01.bin			and later

KCM Models		Camera Firmware	ISP			IP Utility
			ISP Firmware	ISP Resource	ISP Hardware	

KCM-3311	Version	V5.11.17	V1.06.01	V1.06.01	V1.00.11	V4.2.04 and later
KCM-5511	Filename	A1D-311-V5.11.17-AC.upg	ISP-U-0310-V1.06.01.bin			
KCM-5611						
KCM-7311						


KCM Models		Camera Firmware	ISP			IP Utility
			ISP Firmware	ISP Resource	ISP Hardware	
KCM-8111	Version	V5.11.17	V1.07.00	V1.07.00	V1.00.12	V4.2.04 and later
KCM-8211	Filename	A1D-311-V5.11.17-AC.upg	ISP-U-0500-V1.07.00.bin			

Camera Firmware Upgrade Procedure


1. Please unzip the V5.11.17-AC.zip, it included V5.11.17 FW Image, all ISP image files and IP Utility v4.3.03.
2. Run IP Utility.
3. Please select the camera models you want to upgrade in the model list that IP Utility has found. At this point you can see directly within IP Utility which KCM models do not have the latest camera firmware yet.
4. Input camera's account, password and HTTP port number value and click "Firmware Upgrade" on Configuration tool bar.

Account Password Http Port

The following pop-up window will appear.



5. Please save the downloaded firmware files and keep their filenames unchanged.(It is suggested to place the firmware files in the same folder with IP Utility for easy management)
6. Select “Camera/Video Encoder Firmware Image” and “Upgrade the latest firmware” to have IP Utility automatically decide the firmware file <A1D-311-V5.11.17-AC.upg> from the location you give. Please click “Browse” button to choose the specific “Firmware Image Path” folder location, and click “Apply”.



The device needs 5 minutes for FW upgrading, and it will reboot automatically and show return message “Success” after the image upload completes.

7. Then user can check FW Version in IP Utility or login to camera’s Web Configurator by typing the camera’s IP address to the IE browser’s address bar to check if the new camera’s firmware has been correctly loaded into camera.

“Setup”→“System” → “System Info”

If you see the new firmware version there, then everything is correct.

After upgrading the camera firmware, please factory reset the camera to support new features by default.

ISP Firmware Upgrade Procedure


ISP Firmware pack consists of several files – ISP firmware file (.bin) and ISP device resource file (.bin).

Before you start to upgrade the ISP, please check the camera already upgrade to camera latest version **V5.11.17**

1. First, please make sure whether the camera you are trying to upgrade already has the latest ISP firmware or not. To confirm that, please login to camera's Web Configurator by typing the camera's IP address to the IE browser's address bar and click following buttons then:
“Setup”→“System” → “System Info” → “System Log”

You will see ISP items there – ISP Firmware Version, ISP Device Resource Version and ISP Hardware.

Example: KCM-3911




```
System Log :
Starting loading Config File...
Load Config File success.
Loading acap driver.
Loading RTC driver.
Loading PTZ driver.
ISP Firmware Version ISP-F-0200-V1.04.00
ISP Device Resource Version C0200-V1.04.00
ISP Hardware Version ISP-H-0200-V1.00.12
```

2. Please save the downloaded firmware files and keep their filenames unchanged.(It is suggested to place the firmware files in the same folder with IP Utility for easy management)
3. Run IP Utility.
4. Please select the camera models you want to upgrade in the model list that IP Utility has found.
5. Input camera's account, password and http port number value and click "Firmware Upgrade" on Configuration tool bar.


Account Password Http Port [Refresh](#) [Device Settings](#) [Change Network Address](#) [Firmware Upgrade](#) [Config. Backup](#) [Config. Restore](#) [Reset](#) [Save&Reboot](#)

The following pop-up window will appear.




6. For KCM-5111/5211/7111, you need to upgrade two files to complete the ISP firmware upgrading. IP Utility will have popup window to provide you more file type selections.

6.1 please select ISP File Type to “ISP Firmware” and select “Upgrade the latest firmware” to have IP Utility automatically decide the firmware file <ISP-F-0100-V1.03.06.bin> from the location you give.



The device needs 3 minutes for ISP upgrading, and it will reboot automatically and show return message “Success” after the image upload completes.


6.2 Then please select ISP File Type to “ISP Resource” to have IP Utility automatically decide the firmware file <C0100-V1.03.06.bin> from the location you give.




The device needs 1 minute for ISP upgrading, and it will reboot automatically and show return message “Success” after the image upload completes.

7. For KCM-5211E/5311E, if the ISP Firmware Version is 1.01.04, the device needs to upgrade to ISP version 1.01.06 first.


7.1 Please select ISP File Type to “ISP Firmware” and select “Upgrade the latest firmware” to have IP Utility automatically decide the firmware file <ISP-F-0300-V1.01.06.bin> from the location you give; or “Upgrade the specific firmware” if you know which file to use. Please click “Browse” button to choose the specific “Firmware Image File” or “Firmware Image Path” folder location, and click “Apply”. The device needs 3 minutes for ISP upgrading, and it will reboot automatically and show return message “Success” after the image upload completes.



7.2 If the ISP Firmware Version is 1.01.06 or newer, please select “Upgrade the latest firmware” to have IP Utility automatically decide the firmware file <ISP-U-0300-V1.05.01.bin> from the location you give; or “Upgrade the specific firmware” if you know which file to use. Please click “Browse” button to choose the specific “Firmware Image File” or “Firmware Image Path” folder location, and click “Apply”. The device needs 5 minutes for ISP upgrading, and it will reboot automatically and show return message “Success” after the image upload completes.



8. For KCM-3211, KCM-5311 and KCM-7211, there is no new ISP firmware for upgrading.
9. For other KCM models, only one type selection is provided.
Please select “Upgrade the latest firmware” to have IP Utility automatically decide the firmware file from the location you give.



The device needs 5 minutes for ISP upgrading, and it will reboot automatically and show return message “Success” after the image upload completes.

10. After successful upgrade the ISP firmware, please login to camera's Web Configurator by typing the camera's IP address to the IE browser's address bar to check if the new camera's ISP firmware has been correctly loaded into camera.

“Setup” → “System” → “System Info” → “System Log”

If you see the new ISP Firmware and ISP Device Resource version there, then everything is correct.

Download and Documentation

V5.11.17 is official released, the Firmware User Manual and Release Notes are available for download on ACTi.

For camera related utilities, please check the “ACTi Utility”

<http://www.acti.com/Utility>

Support

If you have any question or need additional assistance, please feel free to contact our engineers via our **Customer Help Desk** platform

<http://www.acti.com/CHD>