

Certificate

Issue Date: 2009/04/09
Ref. Report No. ISL-08HE052CE-MA

Product Name: : Network Attached Storage
: VioStor-104; VioStor-104P; VioStor-104V; VioStor-106; VioStor-106P;
VioStor-106V; VioStor-108; VioStor-108P; VioStor-108V; VioStor-109;
VioStor-109P; VioStor-109V; NVR-104; NVR-104P; NVR-104V; NVR-106;
Model Number(s) : NVR-106P; NVR-106V; NVR-108; NVR-108P; NVR-108V; NVR-109; NVR-109P;
NVR-109V; NV-104; NV-104P; NV-104V; NV-106; NV-106P; NV-106V; NV-108;
NV-108P; NV-108V; NV-109; NV-109P; NV-109V
Responsible Party : **QNAP System, Inc.**
Address : 21F, No. 77, Sec. 1, Xintai 5th Rd.,
Xizhi City, Taipei Country, 221, Taiwan, R.O.C
Contact Person :

We, **International Standards Laboratory**, hereby certify that:

The device bearing the trade name and model specified above has been shown to comply with the applicable technical standards as indicated in the measurement report and was tested in accordance with the measurement procedures specified in EUROPEAN COUNCIL DIRECTIVE 2004/108/EC. The device was passed the test performed according to :

Standards:


EN55022: 1998/A1: 2000/A2: 2003; AS/NZS CISPR 22: 2004: Limits and methods of measurement of Radio Interference characteristics of Information Technology Equipment.

EN55024: 1998/A1:2001/A2: 2003; AS/NZS CISPR 24: 2002: Information technology equipment-Immunity characteristics-Limits and methods of measurement.

EN61000-3-2: 2000 /A2:2005; AS/NZS 61000.3.2: 2003: Limits for harmonics current emissions

EN61000-3-3: 1995/A1: 2001; AS/NZS 61000.3.3: 1998: Limits for voltage fluctuations and flicker in low-voltage supply systems.

I attest to the accuracy of data and all measurements reported herein were performed by me or were made under my supervision and are correct to the best of my knowledge and belief. I assume full responsibility for the completeness of these measurements and vouch for the qualifications of all persons taking them.



Jim Chu/ Director

International Standards laboratory

Lung-Tan LAB:

No. 120, Lane 180, San Ho Tsuen, Hsin Ho Rd.
Lung-Tan Hsiang, Tao Yuan County 325, Taiwan
Tel: 886-3-407-1718; Fax: 886-3407-1738

His-Chih LAB:

No. 65, Gu Dai Keng St., Hsichih, Taipei Hsien
22117, Taiwan.

Tel: 886-2-2646-2550; Fax: 886-2-2646-4641